

PMW-F55/F5 Firmware Version V5.11 Release note

April 28th, 2015

This document explains about firmware update of PMW-F55 V5.11 from V5.10 and PMW-F5 V5.11 from V5.00. The latest firmware version of related products is below.

Product name	Latest firmware	Release date
PMW-F55	V5.11	This announcement
PMW-F5	V5.11	This announcement
AXS-R5	V4.1	Aug 8 th , 2014
AXS-512S24	V1.2	June 5 th , 2013
AXS-A512S24/A1TS24	V1.0	Mar 17 th , 2014
AXS-A256S24	V2.0	Mar 26 th , 2015
AXS Utility Software	V1.3	Feb 28 th , 2014
RAW Viewer	V2.2	Feb, 28 th , 2014

This firmware can be updated from V5.10, V5.0, V4.12, V4.11, V4.1, V4.0, V3.0, V2.11, V2.1 and V2.0. When you want to update F55 and F5 from V1.22 and earlier, you must update to V2.0 first. Regarding the procedure and functions about V2.0, please refer to “PMW-F55/F5 Firmware Version V2.0 Release note” which was released on Oct 4th, 2013. And F55 and F5 must not be downgraded to previous versions after updating to V2.11. We couldn't guarantee any troubles after downgrading. All file generated by previous firmware version can be loaded to V5.11 of F55 and F5 but Assignable buttons setting must be set manually.

NOTE: The new Firmware V5.11 for PMW-F55 and PMW-F5 is **only** compatible with AXS-R5 running with Firmware V4.1. If your AXS-R5 has installed an older Version please update to current Firmware V4.1 the same time.

<<Modification from V5.10 of F55 and V5.00 of F5 to V5.11>>

Bug Fix

In V5.10 and V5.00 firmware, sometimes DVF-EL100 unsynchronized display error occurs on 23.98, 24.0, 25.0, 50.0 system frequency. This has been fixed.

<Notification we would like to share>

1. iOS setting for Wi-Fi Remote

While using Wi-Fi Remote by iOS devices and Safari, please turn off Private browse function.

2. All file Support

All files which are created with Firmware V5.11 are **not** compatible with an earlier firmware version.

3. Auto Reboot after ABB and APR on ProRes and DNxHD®

When ABB or APR is executed on ProRes and DNxHD mode, PMW-F55/F5 automatically reboot after displaying “Auto Brack Balance OK” or “RPN Auto Detection OK ” and “Rebooting.....”. This sequence is normal. ABB or APR is correctly executed.

4. Assignable buttons setting does not remain

When you update V5.11 from earlier version or load ALL file generated in earlier version, Assignable buttons setting does not remain. Please set each assignable buttons manually.

<< Version up procedure >>

Please refer to “Version Up Guide for PMW-F55 and F5”.

For PMW-F55: PMW-F55_V511_5.11_6_2015-04-17_20-02-17_firmware.bin

For PMW-F5: PMW-F5_V511_5.11_5_2015-04-17_20-02-23_firmware.bin

EOF